

XB13 Repair Parts

Part Number	Description	4TTB3018 G1000AA	4TTB3024 G1000AA	4TTB3030G 1000AA	4TTB3042 D1000CA	4TTB3048 D1000CA	4TTB3060 D1000CA
FAN04002	FAN; 3 BLADE, ALUMINUM, 23" DIA, 22 DEG PITCH, 0.50" BORE, CCW, 1 SET SCREW-STEEL, SPIDER 0.057 THK, FINISH/PAINT	X	X	X			
FAN04074	FAN; 3 BLADE, ALUMINUM, 27.6" DIA, 19 DEG PITCH, 0.50" BORE, CCW, 1 SET SCREW-STEEL, SPIDER 0.054 THK, FINISH/PAINT				X	X	X
MOT13693	MOTOR; 1/5 HP, 200/230/60/1, 825 RPM, 48 FRAME, PSC, BALL BEARING, CCW, 7.5 MFD CPT AT 370V				X	X	X
MOT14044	MOTOR; 1/8 HP, 200/230/60/1, 850 RPM, 48 FRAME, PSC, SLEEVE BEARING, CCW, 5 MFD CPT AT 370V	X	X	X			
PLU01186	PLUG; SCROLL COMPRESSOR	X	X	X			
SWT03273	SWITCH; HIGH PRESSURE, SPST, OPEN @ 650 PSIG, CLOSE @ 500 PSIG, 88" YELLOW LEAD				X	X	X
SWT03274	SWITCH; HIGH PRESSURE, SPST, OPEN @ 650 PSIG, CLOSE @ 500 PSIG, 75" YELLOW LEAD	X	X	X			
SWT03347	SWITCH; LOW PRESSURE, OPEN @ 50 PSIG CLOSE @ 70 PSIG				X	X	X
SWT03374	SWITCH; LOW PRESSURE, OPEN @ 50 PSIG CLOSE @ 70 PSIG	X	X	X			
VAL07326	VALVE; SERVICE GAS, 0.63 OD X 0.63 OD, BALL VALVE ASSY, BRASS, FEMALE BRAZE TO FEMALE BRAZE, LEFT HAND SERVICE PORT	X	X				
VAL07327	VALVE; SERVICE GAS, 0.75 OD X 0.75 OD, BALL VALVE ASSY, BRASS, FEMALE BRAZE TO FEMALE BRAZE, LEFT HAND SERVICE PORT			X	X		
VAL07328	VALVE, SERVICE GAS, 0.88 OD X 0.88 OD, BALL VALVE ASSY, BRASS, FEMALE BRAZE TO FEMALE BRAZE, LEFT HAND SERVICE PORT					X	X
VAL09293	VALVE; SERVICE LIQUID, 0.38 OD X 0.38 OD, VALVE ASSY	X	X	X	X	X	X
WIR02695	WIRE; HARNESS-SCROLL COMPRESSOR, SINGLE PHASE					X	X
WIR03324	WIRE, PLUG-SCROLL COMPRESSOR				X		